

CARR - 772

1125 POOLE ROAD

mid-19th century

Westminster vicinity

private

1125 Poole Road is a representative farm complex from the mid-to-late nineteenth century. The house is a broadly proportioned brick structure with a wide gabled dormer on the front. The farm buildings include a late nineteenth century bank barn, wagon shed, chicken coop and two early twentieth century silos.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-772

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE:

ORIGINAL USE:

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good ()
Fair () Poor ()

THEME:

STYLE:

DATE BUILT:

COUNTY: CARROLLTOWN: Westminster vicinityLOCATION: 1125 Poole RoadTAX MAP 52 Block 3-4 P-7

COMMON NAME:

FUNCTIONAL TYPE: residenceOWNER: Anthony Zeno CARL L. Hoff
ADDRESS: 1115 Poole Rd
Westminster MD 21157

ACCESSIBILITY TO PUBLIC:

Yes () No () Restricted ()

LEVEL OF SIGNIFICANCE:

Local () State () National ()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
 2. Wall Structure
 - A. Wood: Log () Post and Beam () Balloon ()
 - B. Wood Bearing Masonry: Brick (X) Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other
 3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: common Other:
 4. Roof Structure
 - A. Truss: Wood (X) Iron () Steel () Concrete ()
 - B. Other:
 5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
 6. Engineering Structure:
 7. Other:
- Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells () Wings () Other:
- Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:
- Number of Stories: 2 1/2
- Number of Bays: 5 x 2
- Approximate Dimensions: _____
- Entrance Location: center

THREAT TO STRUCTURE:

No Threat () Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

broadly proportioned
gabled dormer

RELATED STRUCTURES: (Describe)

late 19th c. farm complex bank barn, coop, 2 silos.

STATEMENT OF SIGNIFICANCE:

representative mid-19th c. farmstead

REFERENCES:

1862 Martenet's Map:

1877 LG & S Atlas: Joshua Lockard

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings (X)
Moderately Built Up () Densely-Built Up ()
Residential () Commercial ()
Agricultural () Industrial ()
Roadside Strip Development ()
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

8/83



U.S.G.S. MAP
WESTMINSTER, MD.
1:24000 SCALE

Mapped by the Corps of Engineers, U. S. Army
Edited and published by the Geological Survey



CARR-772

1. 1125 Poole Rd.
2. Carroll Co. Md.
3. J. Getty
4. 11/83
5. Md. Hist. Trust, Annapolis Md.
6. southeast elevation
7. 1/2



CARR. 772

1. 1125 Poole Rd.
2. Carroll Co. Rd.
3. J. Getty
4. 11/63
5. Md. Hist. Trust, Annapolis Rd.
6. farm buildings, south elevati
7. 2/2